## PORSF 11.3.18.1 14



NPDES #1300 Oily Discharge General Permit

Discharge Monitoring Report

Oregon DEQ 2020 SW 4th Avenue, Suite 40

Submit report monthly by

Portland, Oregon 97201

of following month to:

Site/File ID #: 32300

County: MULTNOMAH

Month/Year live

Legal Name: KINDER MORGAN LIQUID TERMINALS LLC

Common Name: LINNTON TERMINAL

Facility Location: 11400 NW ST HELENS RD ; PORTLAND

Monitoring for Oil/Water Separator Oil and Grease Visible Sheen Ethanol and/or MBTE Day (mg/L)Quarterly grab sample, if Daily estimate, when Frequency varies, sec-. Daily, visual present on site and in bulk discharging permit observation No visible sheen at 10 mg/L monthly, 15 No limit No limit Limit nig/L daily max. any time 2 4. 5 6 7 3 9. 10. ]]. 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 28 30 31 Total Max. Average



See Reverse Side for Additional Monitoring and Signature Block

Stormwater Monitoring
Only for facilities required to have NPDES permits for stormwater, per 40 CFR 122.26 Monitoring required for each point identified in the Stormwater Pollution Control Plan

Day	Visible Sheen	Floating Solids (associated with industry)	Total Copper (mg/L)	Total Lead (mg/L)	Total Zinc (mg/L)	pH (S.U.)	Total Suspended Solids (mg/L)
	Daily when discharging, visual observation	Once per month when discharging	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample	Twice per year, grab sample
Limit	No visible sheen	No visible discharge*	0.1 mg/L*	0.4 mg/L*	0.6 mg/l.*	Within 6.0 - to 9.0	130 mg/L*
. 1		. **	-				
2							
3						· ·	
4	· ·			.)			
5							
. 6.	l.			. 1,			
7							
. 8			- 1 - 1 - 1		1		
9	· · · · · · · · · · · · · · · · · · ·			<u> </u>		<del></del>	
11				<u> </u>		-	
12			·		<del></del>		
13					(A) (A)		· · · · · · · · · · · · · · · · · · ·
. 14							
15						<del></del>	
16			*				
17		<del> </del>	1. 1.	9 A M	1.7		
18			2 2 2				
19	· · · · · · · · · · · · · · · · · · ·	i i		. v			· · · · · · · · · · · · · · · · · · ·
20							
21							
22							
23				100			
24							
25							
26							
27							
28							
29					ļ	<del> </del>	
30					ļ	<b>_</b>	
31					ļ <u> </u>		
Total							
Max.		****			ļ	ļ	
Average							

<sup>\*</sup>These are benchmarks, not effluent limits. If benchmarks are exceeded, review/possible revision of Stormwater plan is required. See permit for more details.

## Signature Requirement

I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in
accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted.
Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the
information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that
there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing
violations.

Signature of Responsible Official:	CARRIED
70 PM	1 totale tiel 5
Name and Title (Please Print) Teach	- Yungute / 1019 Scheduler
Date of Signature: 7-6-07	Telephone: 5/13 220 /27/6